


# ATLAS 900 QUADRANT CHR CLEAR GLASS H1950



Note:  
Whole dimension tolerance is  $\pm 5$ .  
Glass dimension tolerance is  $\pm 2$ .