


# ATLAS 1000 QUADRANT CHR CLEAR GLASS



Note:  
Whole dimension tolerance is  $\pm 5$ .  
Glass dimension tolerance is  $\pm 2$ .